

OSA -0599-68

7 February 1968

25X1A

To: [REDACTED]

Subject: LOCAL MODIFICATION TO P/N DN55000 PARACHUTE

Dear Bruce,

Enclosed photos show a modification incorporated to one DN55000 Parachute, by BW-4 personnel.

The modification consists of a four-inch extension to the non-structural fabric beneath the two vertical lift webs.

25X1A

This modification was required in order to permit length adjustment of the lift webbing on pilot [REDACTED]

Prior to the modification, the fabric limited the harness length adjustment and put intolerable pressure on Bob's shoulders.


Sincerely,


[REDACTED]

25X1A

pac

Enclosures: Photos #18414 and #18413




ENVELOPE # 6115 - /
REF NO. 184/13
DATE DEC 14 1967
ON FILE
ORDERED 

25X1A



ENVELOPE # 6115-2
NEG. NO. 18414
DATE SHOT DEC 14 1966
DATE RECEIVED DEC 14 1967
ORDERED BY [REDACTED]

25X1A



ENVELOPE # 6115-1


NEG. NO. 18413


DATE SHOT DEC 14 1967

DATE REPRODUCED
ORDERED





25X1A




ENVELOPE # 6115-/
NEG. NO. 18413
DATE SHOT DEC 14 1967
DATE RECEIVED
ORDERED BY 


25X1A



ENVELOPE # 6115-2i
NEG NO. 18414
DATE DEC 14 1967
TITLE 120
ORDERED BY 

25X1A



ENVELOPE # 6115-2
REC. NO. 18414
DATE SHOT DEC 14 1967
C. C. B. B.
ORDERED BY 

25X1A